luftfederung

Beitrag von „b1971“ vom 7. Januar 2018 um 19:40

Hallo,

ich hatte ein ähnliches Problem mit meinem T2. Als ich am Fr. meinen Touareg für die Rückreise aus dem Ski Urlaub klarmachte, bekam ich die Fehlermeldung "Stop! Fehler Fahrwerk" angezeigt. Ein löschen des Fehlers über VCDS half nicht. Da sich das Fahrzeug auf gleichmäßiger Höhe im Offroad Niveau befand und weich abfederte, bin ich trotzdem die 950km gemütlich nach Hause gefahren...

Heute habe ich festgestellt, dass die Sicherung (40A) für den Kompressor durch war. Nachdem ich die ausgetauscht habe, war wieder alles in Ordnung...

Aber: Was kann die Ursache dafür sein? Ich hätte ein besseres Gefühl, wenn ich wüsste warum die Sicherung durchgebrannt ist.

Viele Grüße,
Bernd

VCDS Fehler:
Address 34: Level Control (J197) Labels:. 7P0-907-553.clb
Part No SW: 7P0 907 553 N HW: 7P0 907 553 N
Component: PASM H01 1550
Revision: 00000000 Serial number: 00000122470430
Coding: 14210001
Shop #: WSC 31414 790 00001
ASAM Dataset: EV_PASMConti 001004
ROD: EV_PASMConti.rod
VCID: 42B37B08D56B1256C7-8016

1 Fault Found:
0644 - Level control system
C10D3 07 [008] - Mechanical Failure
Intermittent - Confirmed - Tested Since Memory Clear
Freeze Frame:
Fault Status: 00000001
Fault Priority: 9
Fault Frequency: 85
Reset counter: 1

Mileage: 330752 km
Date: 2019.02.26
Time: 30:05:05

Default: 60
Default: 8E
Default: 00